

July 4, 1976

MODEL TU-907

ULTRASONIC WEDGE BONDER

Mech-El Industries, Inc.  
73 Pine Street  
Woburn, Massachusetts  
01801

-TABLE OF CONTENTS-

	<u>Page</u>
Unpacking-----	1
Setup Procedure-----	2
Checkout-----	3-4
Bonding-----	5
Troubleshooting-----	6-7-8
Bonding Troubleshooting-----	9
Figure #1 - Front View-----	10
Figure #2 - Rear View-----	11
Figure #3 - Side View-----	12
Figure #4 - Shipping Bracket Removal #AI-35---	13
Figure #5 - Bonding Head Front View-----	14
Figure #6 - Lower Front View-----	15
Reset Position of Clamp Arm - #AI-36-----	16
TU-907 Black Arm Assembly - #AI-42-----	17
60° Feed - #AI-37-----	18
Heated Work Station-Mechanical Clamp #AI-34-	19
Spotlight Adjustment - #AI-41-----	20

	<u>Page</u>
Spare Parts List-----	21-22
TU-907 Schematic #E-0022-----	23
TU-907 AC Wiring - #E-0023-----	24
Heat Card Schematic - #E-0026-----	25
Power Supply Schematic - #E-0027-----	26
Temperature Board Layout #390-0041-----	27

-----

## UNPACKING

1. Remove aluminum "L" shaped shipping bracket connected to the upper weight rod and top of the damper at the back of the machine. (See Figure #4)
2. Remove the foam from the Z lever at the front of the machine.
3. Remove tubing from under gross motion positioning plate.
4. Remove cover on top rear of the machine. Remove tagged nylon shipping wedge from head pivot. (See Figure #4).
5. Remove two cap packing screws that secure the positioner plate.

## SETUP

1. Assemble microscope and lights. Mount to one inch black hollow rod at the top of the machine. Tighten two 10-32 set screws to secure microscope to rod.
2. Plug in machine.
3. Main power "on". See Figure #1.
4. Generator "on". See Figure #1.
5. Place workstation on gross motion plate.

## OPTIONAL-WITH VACUUM LOCKDOWN

1. Connect vacuum (20 in. Hg. vacuum) to fitting at the left rear of the machine marked "vacuum". See Figure #2. Turn on vacuum.
2. Vacuum lockdown switch for workstation is located at the lower left front of the machine. See Figure #1.

## CHECKOUT

1. Cycle light "off" (located on head behind workstation). See Figure #1.
2. Set Channel 1 and 2 power and time to "3". Set Hi-Lo power switch on "Lo". See Figure #1.
3. Press Cycle button. See Figure #1.
  - (a) Generator meter should deflect (firing first bond). Cycle light "on".
  - (b) Clamps open.
  - (c) Loop height adjust coil, Figure #1, will now be energized.
4. Release cycle button.
  - (a) Clamp motion arm moves up.
5. Press Cycle in again and hold.
  - (a) Generator meter should deflect (second bond fires).
  - (b) Clamp should close and then pull back terminating wire at heel of second bond.
  - (c) Loop height coil "off".
  - (d) Cycle light "out".
6. Release cycle button.
  - (a) Clamps return to reset position feeding a tail through the hole in the wedge.
7. Place appropriate wedge for wire size to be bonded in transducer using tool height gauge supplied with bonder. See Figure #2.
8. Check transducer position. Center of transducer to be in line with bottom of black arm. See Figure #5.

9. Place wire on spoolholder and thread. Wire is fed off the bottom of the 1/2" spool through the hole in the transducer, through wire clamps over wire guide at rear of clamps and through the hole in the wedge. See Figure #8 for 60 degree feeding.
10. Tune generator for null by turning adjust rod between fuses in the rear of the machine. For proper nulling procedure, see UTI manual enclosed.
11. Loosen set screw on side of workstation, See Figure #5. Adjust set screw located at the bottom of the pedestal, turning screw in will raise the workstation, turning screw out will lower the workstation (1 turn is 1/32"). Adjust to 2.50" from the bottom of the workstation to bonding surface. See Figure #5.
12. Set weight of bonding head using a gram gauge (.001" wire approximately 28g). Main power "off". Lower Z lever all the way down with workstation in place. Adjust weight with wedge touching the work. Measure the force necessary to pick up wedge. Adjust by using sliding counterweight, Figure #2. Turn main power switch "on".
13. With machine in reset position, check position of tail adjust screw and clamp motion limit screw. See Figure #6.
14. For machine with heated workstage (Figure #7), turn on heat switch. Check calibrate temperature of heated workstation with pyrometer. Workstation should equal 1/2 digital temperature readout (500 on dial = 250<sup>o</sup> on workstation).
  - (a) To calibrate workstation, remove stainless steel cover (See Figure 1). The heat card is the PCB located behind the generator. The calibration pot is the trimpot located in front of the I.C. Calibrate the dial to correspond with the pyrometer by turning the trimpot screw. The light should be on the threshold when the dial is two times the work temperature.

## BONDING

1. Lower Z lever (Figure #1) down to its bottom stop. Make first bond.
2. Raise Z lever--set loop height to desired level (approximately 1/2 the length of loops) with nylon "looping" screw. See Figure #5.
3. Move x-y positioner and bring down Z lever again to make a second bond. Bonding sequence is controlled by a photocell (Figure #2) when the Z lever is lowered. No search. No buttons required to make the bonds.
  - (a) If machine does not cycle with Z lever, photocell flag in rear of machine is too high.
  - (b) If machine does not cycle with cycle push button, photocell flag is too low.
4. Raise Z lever all the way up to reset position.
5. Clamp Set-up. Turn pot on logic card for maximum force on clamp coil (See Figure #3). Cycle machine with push button and hold in reset position. If clamps do not close, screw in clamp adjust screw opposite coil slug just enough to close. (See Figure #5). Turn down pot on logic card so force on clamp is approximately 80 to 100g. After adjusting clamp, tighten nylon set screw to lock adjust screw. Nylon tip set screw is located on top of right clamp arm.
6. Adjust ultrasonic power for first and second bond for optimum strength. To test strength, use Mech-El Bond Tester, Model BT-202.

### TROUBLESHOOTING


- |                               |    |                                       |    |  |
|-------------------------------|----|---------------------------------------|----|--|
| Tail too short                | 1) | Tail adjust screw incorrect           | 1) | Turn tail adjust screw clockwise (down).   |
| Tail too long                 | 1) | Tail adjust screw incorrect           | 1) | Turn tail adjust screw counter-clockwise (up).   |
| Tail not centered under wedge | 1) | Transducer not aligned properly       | 1) | Loosen transducer clamp screw (See #A.I. 42 - 290-0278) and align center of tool to center of clamp opening. Align transducer so tool is perpendicular, center of transducer to be in line with bottom of black arm (See Figure #5). |
| Inconsistent Tail             | 1) | Clamp pressure not adjusted properly. | 1) | Adjust clamp pressure pot (See Figure #3) for approximately 80-100g of pressure at clamps.   |
|                               | 2) | Too much power on second bond         | 2) | Decrease second bond power-time setting, if second bond deformation appears to be excessive (over 2 wire diameters).   |
|                               | 3) | No cotton in transducer               | 3) | Insert a small piece of cotton into hole of transducer so as to apply a slight amount of drag on the wire.   |

- |   |  |    |  |
|---|--|----|--|
| 4)  | Clamp motion screw not adjusted properly               | 4) | At loop position clearance between bottom of clamp motion nylon screw and rubber bumper should be approximately 1/32" (See Figure #6).   |
| 5)  | Wire feeding while wedge is on the work                | 5) | After second bond has been made, if the Z lever is returned to its reset position in a brisk manner, the wire will not feed on the work.   |
| 6)  | Wire fed back through wedge before second bond is made | 6) | Set loop height so the wire does not feed through the wedge from loop to second bond.  |
| Tail does not feed  |  | 1) | Decrease tension on spring (See Figure #2).  |
| 2)  | Wedge plugged  | 2) | Unplug wedge.  |
| 3)  | Tail adjust screw not properly set                     | 3) | After first bond, clamp arm should pivot up. If it does not, tail adjust screw may be too high.  |
| Tail does not pull  |  | 1) | Increase tension of clamp motion spring.   |
| 2)  | Clamp motion limit screw down too far.                 | 2) | Turn screw up. See Figure #6 for proper set up procedure.  |
| Machine cycles properly with cycle button but does not cycle with Z lever |  | 1) | Adjust flag, loosen flag adjust screw (Figure #2) and slowly lower flag until cycle light in front of the machine turns "on", push flag up 1/32" from this position. Tighten lock screw. |

- |  |  |
|--|--|
| 2) Workstage too low   | 2) Adjust workstage height to 2.5" from base of bonding surface, (See Figure #5).  |
| Workstage does not heat up (for machines with heated workstage)  | 1) Heat switch not "on"<br>2) Thermocouple open<br>3) Heater open<br>4) Workstage not plugged in<br>5) Fuse blown<br>6) Heat card out of connector (under stainless steel cover) |
| 1) Check heat on off switch.   | 1) Check heat on off switch.   |
| 2) Check thermocouple for an open with ohm meter, Pins C and H on workstation plug.  | 2) Check thermocouple for an open with ohm meter, Pins C and H on workstation plug.  |
| 3) Check heaters for open with ohm meter, Pins A-E on workstation plug.  | 3) Check heaters for open with ohm meter, Pins A-E on workstation plug.  |
| 4) Check workstation plug.   | 4) Check workstation plug.   |
| 5) Check fuse in rear of machine.  | 5) Check fuse in rear of machine.  |
| 6) Remove plug from outlet, remove stainless steel cover from right side of machine. Make sure heat card in rear of generator is firmly seated into its connector. | 6) Remove plug from outlet, remove stainless steel cover from right side of machine. Make sure heat card in rear of generator is firmly seated into its connector.               |
| Workstage not calibrated (for machines with heated workstage)  | 1) To calibrate workstage, adjust potentiometer on heat control card so the controller reads twice the temperature of the stage. 500 on dial = 250°C.                            |
| 1) Calibration potentiometer on heat card set wrong  | 1) Calibration potentiometer on heat card set wrong  |
| Workstage runs away (for machines with heated workstage)   | 1) Check for shorted thermocouple.   |
| 1) Thermocouple shorted  | 1) Thermocouple shorted  |
| 2) Defective card  | 2) Consult factory.  |

BONDING TROUBLESHOOTING

- |                                    |                                     |  |
|------------------------------------|-------------------------------------|--|
| First bond does not stick          | 1) Power or time too low            | 1) Adjust time and power settings "A" Channel.   |
|                                    | 2) Weight too low                   | 2) Adjust bond weight to approximately 28g for .001" wire. <sup>0.002</sup> 25.4 <sup>0.004</sup> 25.4 <sup>0.007</sup> 25.4             |
|                                    | 3) Work loose                       | 3) Check piece being bonded, make sure it is tight.  |
|                                    | 4) Poor bonding surface             | 4) Try a known good substrate on unit.   |
|                                    | 5) Generator not tuned              | 5) Tune generator. See UTI manual.   |
| Too much deformation on first bond | 1) Power or time too high           | 1) Decrease power and/or time on "A" Channel.  |
|                                    | 2) Weight too high                  | 2) Check and adjust, if necessary.   |
|                                    | 3) Loop height too low              | 3) Check loop height. After first bond is made, release Z lever. Adjust loop adjustment so wedge is approximately .010" above substrate. |
| Second bond does not stick         | 1) Not enough power, time or weight | 1) Adjust time and power "B" channel. Adjust weight for approximately 28g for .001" wire.  |
|                                    | 2) Generator not tuned              | 2) Check and tune, if necessary. See UTI manual for tuning procedure.  |
|                                    | 3) Poor bonding surface             | 3) Try a known good substrate on unit.   |



Hi-Low Power Switch

set power and time at 3  
for initial setup

Power Switch

Z lever

Vacuum Switch  
(optional)

---Cycle Light---  
---Cycle Button---

FIGURE #1






FIGURE #2



Clamp Pressure  
Adjust Pot.

FIGURE #3

DATE	SYM	REVISION RECORD	AUTH	DR.	CK.



TOLERANCES (EXCEPT AS NOTED)		MECH-EL INDUSTRIES INC	
DECIMAL	±	SCALE	DRAWN BY T8
FRACTIONAL	±		APPROVED BY
ANGULAR	±	TITLE SHIPPING BRACKET REMOVAL	
		DATE	DRAWING NUMBER
		6-10-76	AI 35





FIGURE #5




Rotor Drag Screw


--Positioner Drag Screw

FIGURE #6

DATE	REVISION	RECORD	APPROVED	CEL



CLAMP ARM RESET POSITION



CLAMP ARM HOLD BACK POSITION


TOLERANCES (UNLESS OTHERWISE SPECIFIED)	MECH-EL INDUSTRIES INC	
GENERAL	SCALE	DRAWN BY T.B.
±	—	APPROVED BY
FUNCTIONAL	TITLE	
±	RESET POSITION OF CLAMP ARM	
ANGULAR	DATE	DRAWING NUMBER
±	6-10-76	A.I. 36



DATE	SYM	REVISION RECORD	AUTH.	DR.	CK.

CLAMP OPENING  
ADJ.

WIRE




CLAMP SOLENOID

HEAVY RIBBON 60°

WIRE

CLAMP OPENING ADJ.



CLAMP SOLENOID

STANDARD RIBBON 60°


TOLERANCES (EXCEPT AS NOTED)		MECH-EL INDUSTRIES INC.	
DECIMAL	± —	SCALE	—
FRACTIONAL	± —	DRAWN BY	TBEATKE
ANGULAR	± —	APPROVED BY	
TITLE		60° FEED	
DATE	6-11-76	DRAWING NUMBER	A.I. 37



DATE	SYM	REVISION RECORD	AUTH.	DR.	CK.

FRONT TO BACK

LEFT TO RIGHT



LOCK SCREW

TOLERANCES (EXCEPT AS NOTED)		MECH-EL INDUSTRIES INC	
DECIMAL	±	SCALE	—
FRACTIONAL	±	DRAWN BY	TB
ANGULAR	±	APPROVED BY	
TITLE		SPOT LIGHT ADJUSTMENT	
DATE	6-11-76	DRAWING NUMBER	9I 41

SPARE PARTS LIST  
TU-907


<u>Part No.</u>	<u>Description</u>	<u>Quantity</u>
190-0012	Switch	1
190-0032	3-Amp Fuse	1
190-0064	Solenoid SP-37	2
190-0089	Fluorescent Light Bulb W-31	1
190-0090	Fluorescent Light Transformer	1
190-0208	Solenoid SP-50	1
190-0229	Switchcraft Switch	1
190-0234	Photocell	1
191-0324	1/2 Amp Fuse	2
191-0326	LED	1
290-0280	Spring	1
890-1240	Adjust Screw	2
	2-56 Set Screw 1/16" long	2
<u>Lower Positioner Bearing and Rod Assembly:</u>		
291-0323	Spherical Bearing	1
891-0121	Guide Motion Rod	1
<u>Middle Positioner Bearing:</u>		
291-0323	Spherical Bearing	1
<u>Upper Positioner Bearing and Rod Assembly:</u>		
291-0322	Spherical Bearing	1
891-0122	Rod Motion	1

SPARE PARTS LIST  
TU-907

<u>Part No.</u>	<u>Description</u>	<u>Quantity</u>
<u>Logic Board Components:</u>		
190-0204	Transistor #GPS-A05	2
191-0327	I.C. #CD4011	2
191-0328	I.C. #CD4027	2
191-0329	I.C. #CD4047	2
191-0330	I.C. #CD3082	1
191-0331	Transistor MJE 1101	2
<u>Heat Card Components for Machine with Heated Work Station:</u>		
190-0158	I.C. #U6B 7739393	1
190-0293	Triac #SC45B GE	1
190-0360	Heater	1
190-0361	Thermocouple	1
<u>Parts Listed Below are for Export and/or Multiple Orders:</u>		
390-0190	Logic Card	1
<u>For TU-907 with Heated Work Station</u>		
390-0041	Heat Card	1
190-0036	25AT UTI Transducer	1
190-0273	5 Watt UTI Generator	1
390-0188	MEI Power Supply Card	1







NOTE :


- ALL PNP TRANSISTORS    GPS A55
- ALL NPN TRANSISTORS    GPS A05
- IC                            μ6B-7739393
- DIODES ARE                1N4002

TOLERANCES UNLESS SHOWN		MECH-EL INDUSTRIES INC	
REV. NO.	2	DESIGNED BY	A.G.
APPROVED BY		CHECKED BY	NONE
TITLE		HEAT CARD SCHEMATIC	
DATE	9 MAR 73	DRAWN BY	E-0026
QUANTITY	2		

REV	1	10/10/74	1
REV	2	11/10/74	1
REV	3	12/10/74	1
REV	4	1/11/75	1
REV	5	2/11/75	1
REV	6	3/11/75	1
REV	7	4/11/75	1
REV	8	5/11/75	1
REV	9	6/11/75	1
REV	10	7/11/75	1
REV	11	8/11/75	1
REV	12	9/11/75	1
REV	13	10/11/75	1
REV	14	11/11/75	1
REV	15	12/11/75	1
REV	16	1/12/76	1
REV	17	2/12/76	1
REV	18	3/12/76	1
REV	19	4/12/76	1
REV	20	5/12/76	1
REV	21	6/12/76	1
REV	22	7/12/76	1
REV	23	8/12/76	1
REV	24	9/12/76	1
REV	25	10/12/76	1
REV	26	11/12/76	1
REV	27	12/12/76	1
REV	28	1/1/77	1
REV	29	2/1/77	1
REV	30	3/1/77	1
REV	31	4/1/77	1
REV	32	5/1/77	1
REV	33	6/1/77	1
REV	34	7/1/77	1
REV	35	8/1/77	1
REV	36	9/1/77	1
REV	37	10/1/77	1
REV	38	11/1/77	1
REV	39	12/1/77	1
REV	40	1/2/78	1
REV	41	2/2/78	1
REV	42	3/2/78	1
REV	43	4/2/78	1
REV	44	5/2/78	1
REV	45	6/2/78	1
REV	46	7/2/78	1
REV	47	8/2/78	1
REV	48	9/2/78	1
REV	49	10/2/78	1
REV	50	11/2/78	1
REV	51	12/2/78	1
REV	52	1/3/79	1
REV	53	2/3/79	1
REV	54	3/3/79	1
REV	55	4/3/79	1
REV	56	5/3/79	1
REV	57	6/3/79	1
REV	58	7/3/79	1
REV	59	8/3/79	1
REV	60	9/3/79	1
REV	61	10/3/79	1
REV	62	11/3/79	1
REV	63	12/3/79	1
REV	64	1/4/80	1
REV	65	2/4/80	1
REV	66	3/4/80	1
REV	67	4/4/80	1
REV	68	5/4/80	1
REV	69	6/4/80	1
REV	70	7/4/80	1
REV	71	8/4/80	1
REV	72	9/4/80	1
REV	73	10/4/80	1
REV	74	11/4/80	1
REV	75	12/4/80	1
REV	76	1/5/81	1
REV	77	2/5/81	1
REV	78	3/5/81	1
REV	79	4/5/81	1
REV	80	5/5/81	1
REV	81	6/5/81	1
REV	82	7/5/81	1
REV	83	8/5/81	1
REV	84	9/5/81	1
REV	85	10/5/81	1
REV	86	11/5/81	1
REV	87	12/5/81	1
REV	88	1/6/82	1
REV	89	2/6/82	1
REV	90	3/6/82	1
REV	91	4/6/82	1
REV	92	5/6/82	1
REV	93	6/6/82	1
REV	94	7/6/82	1
REV	95	8/6/82	1
REV	96	9/6/82	1
REV	97	10/6/82	1
REV	98	11/6/82	1
REV	99	12/6/82	1
REV	100	1/7/83	1
REV	101	2/7/83	1
REV	102	3/7/83	1
REV	103	4/7/83	1
REV	104	5/7/83	1
REV	105	6/7/83	1
REV	106	7/7/83	1
REV	107	8/7/83	1
REV	108	9/7/83	1
REV	109	10/7/83	1
REV	110	11/7/83	1
REV	111	12/7/83	1
REV	112	1/8/84	1
REV	113	2/8/84	1
REV	114	3/8/84	1
REV	115	4/8/84	1
REV	116	5/8/84	1
REV	117	6/8/84	1
REV	118	7/8/84	1
REV	119	8/8/84	1
REV	120	9/8/84	1
REV	121	10/8/84	1
REV	122	11/8/84	1
REV	123	12/8/84	1
REV	124	1/9/85	1
REV	125	2/9/85	1
REV	126	3/9/85	1
REV	127	4/9/85	1
REV	128	5/9/85	1
REV	129	6/9/85	1
REV	130	7/9/85	1
REV	131	8/9/85	1
REV	132	9/9/85	1
REV	133	10/9/85	1
REV	134	11/9/85	1
REV	135	12/9/85	1
REV	136	1/10/86	1
REV	137	2/10/86	1
REV	138	3/10/86	1
REV	139	4/10/86	1
REV	140	5/10/86	1
REV	141	6/10/86	1
REV	142	7/10/86	1
REV	143	8/10/86	1
REV	144	9/10/86	1
REV	145	10/10/86	1
REV	146	11/10/86	1
REV	147	12/10/86	1
REV	148	1/11/87	1
REV	149	2/11/87	1
REV	150	3/11/87	1
REV	151	4/11/87	1
REV	152	5/11/87	1
REV	153	6/11/87	1
REV	154	7/11/87	1
REV	155	8/11/87	1
REV	156	9/11/87	1
REV	157	10/11/87	1
REV	158	11/11/87	1
REV	159	12/11/87	1
REV	160	1/12/88	1
REV	161	2/12/88	1
REV	162	3/12/88	1
REV	163	4/12/88	1
REV	164	5/12/88	1
REV	165	6/12/88	1
REV	166	7/12/88	1
REV	167	8/12/88	1
REV	168	9/12/88	1
REV	169	10/12/88	1
REV	170	11/12/88	1
REV	171	12/12/88	1
REV	172	1/13/89	1
REV	173	2/13/89	1
REV	174	3/13/89	1
REV	175	4/13/89	1
REV	176	5/13/89	1
REV	177	6/13/89	1
REV	178	7/13/89	1
REV	179	8/13/89	1
REV	180	9/13/89	1
REV	181	10/13/89	1
REV	182	11/13/89	1
REV	183	12/13/89	1
REV	184	1/14/90	1
REV	185	2/14/90	1
REV	186	3/14/90	1
REV	187	4/14/90	1
REV	188	5/14/90	1
REV	189	6/14/90	1
REV	190	7/14/90	1
REV	191	8/14/90	1
REV	192	9/14/90	1
REV	193	10/14/90	1
REV	194	11/14/90	1
REV	195	12/14/90	1
REV	196	1/15/91	1
REV	197	2/15/91	1
REV	198	3/15/91	1
REV	199	4/15/91	1
REV	200	5/15/91	1
REV	201	6/15/91	1
REV	202	7/15/91	1
REV	203	8/15/91	1
REV	204	9/15/91	1
REV	205	10/15/91	1
REV	206	11/15/91	1
REV	207	12/15/91	1
REV	208	1/16/92	1
REV	209	2/16/92	1
REV	210	3/16/92	1
REV	211	4/16/92	1
REV	212	5/16/92	1
REV	213	6/16/92	1
REV	214	7/16/92	1
REV	215	8/16/92	1
REV	216	9/16/92	1
REV	217	10/16/92	1
REV	218	11/16/92	1
REV	219	12/16/92	1
REV	220	1/17/93	1
REV	221	2/17/93	1
REV	222	3/17/93	1
REV	223	4/17/93	1
REV	224	5/17/93	1
REV	225	6/17/93	1
REV	226	7/17/93	1
REV	227	8/17/93	1
REV	228	9/17/93	1
REV	229	10/17/93	1
REV	230	11/17/93	1
REV	231	12/17/93	1
REV	232	1/18/94	1
REV	233	2/18/94	1
REV	234	3/18/94	1
REV	235	4/18/94	1
REV	236	5/18/94	1
REV	237	6/18/94	1
REV	238	7/18/94	1
REV	239	8/18/94	1
REV	240	9/18/94	1
REV	241	10/18/94	1
REV	242	11/18/94	1
REV	243	12/18/94	1
REV	244	1/19/95	1
REV	245	2/19/95	1
REV	246	3/19/95	1
REV	247	4/19/95	1
REV	248	5/19/95	1
REV	249	6/19/95	1
REV	250	7/19/95	1
REV	251	8/19/95	1
REV	252	9/19/95	1
REV	253	10/19/95	1
REV	254	11/19/95	1
REV	255	12/19/95	1
REV	256	1/20/96	1
REV	257	2/20/96	1
REV	258	3/20/96	1
REV	259	4/20/96	1
REV	260	5/20/96	1
REV	261	6/20/96	1
REV	262	7/20/96	1
REV	263	8/20/96	1
REV	264	9/20/96	1
REV	265	10/20/96	1
REV	266	11/20/96	1
REV	267	12/20/96	1
REV	268	1/21/97	1
REV	269	2/21/97	1
REV	270	3/21/97	1
REV	271	4/21/97	1
REV	272	5/21/97	1
REV	273	6/21/97	1
REV	274	7/21/97	1
REV	275	8/21/97	1
REV	276	9/21/97	1
REV	277	10/21/97	1
REV	278	11/21/97	1
REV	279	12/21/97	1
REV	280	1/22/98	1
REV	281	2/22/98	1
REV	282	3/22/98	1
REV	283	4/22/98	1
REV	284	5/22/98	1
REV	285	6/22/98	1
REV	286	7/22/98	1
REV	287	8/22/98	1
REV	288	9/22/98	1
REV	289	10/22/98	1
REV	290	11/22/98	1
REV	291	12/22/98	1
REV	292	1/23/99	1
REV	293	2/23/99	1
REV	294	3/23/99	1
REV	295	4/23/99	1
REV	296	5/23/99	1
REV	297	6/23/99	1
REV	298	7/23/99	1
REV	299	8/23/99	1
REV	300	9/23/99	1
REV	301	10/23/99	1
REV	302	11/23/99	1
REV	303	12/23/99	1
REV	304	1/24/00	1
REV	305	2/24/00	1
REV	306	3/24/00	1
REV	307	4/24/00	1
REV	308	5/24/00	1
REV	309	6/24/00	1
REV	310	7/24/00	1
REV	311	8/24/00	1
REV	312	9/24/00	1
REV	313	10/24/00	1
REV	314	11/24/00	1
REV	315	12/24/00	1
REV	316	1/25/01	1
REV	317	2/25/01	1
REV	318	3/25/01	1
REV	319	4/25/01	1
REV	320	5/25/01	1
REV	321	6/25/01	1
REV	322	7/25/01	1
REV	323	8/25/01	1
REV	324	9/25/01	1
REV	325	10/25/01	1
REV	326	11/25/01	1
REV	327	12/25/01	1
REV	328	1/26/02	1
REV	329	2/26/02	1
REV	330	3/26/02	1
REV	331	4/26/02	1
REV	332	5/26/02	1
REV	333	6/26/02	1
REV	334	7/26/02	1
REV	335	8/26/02	1
REV	336	9/26/02	1
REV	337	10/26/02	1
REV	3		



NOTE  
 (1) IC SOCKET # 14 DIP



TOLERANCES (UNLESS SHOWN OTHERWISE)		MECH-EL INDUSTRIES INC	
RESISTORS	±	SCALE	2:1
CAPACITORS	±	DATE OF APPROVAL BY	AG
TITLE		TEMPERATURE CONTROL BOARD	
DATE	6 APR 73	DESIGNED BY	
DRAWING NUMBER		390-0041	